

B2.5 Proposed Monitoring

Emission Point A: rubber fume

Ref PG 6/28(11) Table 4.1 / advice from EA: Manual extractive test to determine emission level – if below WEL, no further monitoring proposed.

Emission Point A: process dust

Ref PG 6/28(11) Table 4.1 / advice from EA: Manual extractive test to determine emission level – if below 50mg/Nm³, no further monitoring proposed.

Emission Point B: Spray Booth

Ref PG 6/28(11) Table 4.2: Annual manual extractive testing for non abated releases

Emission Point C: Rubber fume

Ref PG 6/28(11) Table 4.1/ advice from EA: Carry out manual extractive test to determine emission level – if below WEL, no further monitoring proposed.

Emission Point C: process dust

Ref PG 6/28(11) Table 4.1 / advice from EA: Manual extractive test to determine emission level – if below 50mg/Nm³, no further monitoring proposed.

Emission Point D: Polyurethane casting

Ref PG 6/29(12) Section 3.10 No testing proposed if below threshold for triviality exemption.